

T2 Temperature Sensor

Sensor is used either for temperature monitoring or for thermal compensation of strain sensors. It can be glued to any monitoring steel surface.



Main technical parameters:

Measurement range, °C	-50...+80
Resolution, °C	0.1
Accuracy, %	0.1
Wavelength range, nm	1500 - 1600
Materials	Aluminium
Connectors	FC/APC or without connectors
Dimensions, mm	26 x 5 x 2
Cable thickness, mm	0.9/3
Weight, g	2.5

Optromix, Inc.

2464 Massachusetts Ave, Suite 220 Cambridge, MA 02140
office: +1-617-558-9858, e-mail: info@optromix.com